



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER JOHN R. BAZA
Executive Director Division Director

Inspection Report
Minerals Regulatory Program
June 4, 2008

Supervisor SLW

Mine Name: Rhea-Rae	Permit Number: S0190064
Operator Name: Black Gold Organic Fertilizer Inc.	Inspection Date: 05/09/08
Inspector(s): Tom Munson	Time: 10 AM-11:30AM
Other Participants: none	Mine Status: inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection: As a new inspector to this area, this inspection was mainly to find the site and assess the amount of disturbance.

Bond Amount: \$20,700 (escalation year 2010)

Permit fee: Up to date

Inspection Summary: The site was visible from I-70. Arriving on onsite, it was immediately apparent that the site had not been maintained or was in a safe and secure condition. There was 5 or 6 areas of disturbance mainly related to the accumulation of metal junk including motors, metal storage tanks, empty semi-trailers, conveyors, crushers. The site contained a lined pond, two rubber bladders full of water?, 20 barrels? of questionable material that was in open barrels, an oil and grease metal tray full of oil and grease products also not protected from the elements and full of H2O and spilled oil, decomposing pallets of chemicals, 9 barrels full of an unknown substance, multiple open buckets of what appears to be lubricants.

Photos were taken to document site conditions.

Conclusions and Recommendations:

A cessation order is being issued for failure to contain hazardous material on site.

Inspector's Signature Tom Munson

TM:pb

cc: (OPERATOR)

Willstokes@utah.gov

O:\M019-Grand\S0190064-RheaRae\inspections\insp-S190064-05092008.doc